

## Bimonthly Solicitation Questions and Responses Report

Bimonthly Solicitation Title: September 2020

Bimonthly Solicitation Month & Year: September 2020

### Projects

Solicitation ID	Project ID	Project Description
No records to display		

### Questions and Responses

**Q1:** Please confirm "Ability and experience compiling mapping and digital terrain data in MicroStation 3D files" in the Consultant Requirements is correct.

**R1:** Confirmed

### Projects

Solicitation ID	Project ID	Project Description
NE-01	1146-75-10	Reconstruction, Expansion

### Questions and Responses

**Q1:** Will consultants perform "non-destructive evaluation and testing, structural inspection, structural design, bridge rehabilitation, and bridge maintenance" listed in the Consultant Requirements?

**R1:** No

### Projects

Solicitation ID	Project ID	Project Description
No records to display		

### Questions and Responses

No Records to display

### Projects

Solicitation ID	Project ID	Project Description
SW-02	5710-00-02	Treat the pavement with a mill and overlay. Begin the project at the end of 5710-00-71. Update curb ramps as needed to meet ADA requirements. Place a concrete overlay on B-62-51. Investigate need for real estate acquisition at curb ramps.

## Bimonthly Solicitation Questions and Responses Report

### Questions and Responses

**Q1:** Can you clarify if a historical investigation will be required?

**R1:** The consultant will prepare a request for screening form. A historical survey is possible.

### Projects

Solicitation ID	Project ID	Project Description
SW-03	5780-03-02	Treat the pavement with a mill and overlay. Begin project at end of 5780-03-61. Update curb ramps as needed to meet ADA requirements. Replace guard rail end terminals as needed. Treat B-12-103 with concrete surface repair and a concrete deck overlay. Investigate the need for real estate acquisition at curb ramps.
SW-03	5780-03-31	Treat the pavement with a mill and overlay. Update curb ramps as needed to meet ADA requirements. Replace guard rail terminals as needed. Replace structures B-12-817, B-12-697, and B-12-698.

### Questions and Responses

**Q1:** Will structures design and survey report be performed by the consultant or WisDOT?

**R1:** WisDOT